

Tech Ops Safety Action Program (T-SAP)

[Team Login](#)[T-SAP Main](#)

T-SAP Advisory: TSAP-14-001

[Email](#) | [Subscribe](#) | [Unsubscribe](#) | [Print](#)

Status: Active

Effective Date: 05/09/2014

Facility Information

NAS Category:	Equipment:	Locations:	Fac ID Code:
COMMUNICATION	ATCT	ALL	N/A

Event Information

Title: ..

Problem: It was reported to T-SAP that the portable Disan Signal Light Gun is not focused properly to emit light at the intensity necessary for use.

Symptom: The portable Disan Signal Light Gun was reported unusable by air traffic/technicians at some locations. Tests determined the gun was not visible from all areas of the airport.

Solution: A full engineering study is being conducted and a long-term solution should be available around December 2015. If the portable Disan Signal Light Gun does not meet your facility's needs at this time, please contact one of the POCs listed below.

Remarks: If you are an eligible T-SAP submitter and have additional information that pertains to the subject of this document, we encourage you to file your own T-SAP report. Information you possess may be unknown to the E RC and could augment existing reports. These additional reports may contain important safety information that allows us to identify trends and issues currently not perceived as systemic problems, or reveal a perspective that has not been considered.

POC Information

	Email	Title	Phone
Technical POC1:	mark.baumgartner@faa.gov	Program Implementation Lead, AJW-22	405-954-3364
Technical POC2:	brian.ctr.wayland@faa.gov	Engineer, AJW-22	405-954-8472
Supply POC:			

[View Attachments](#)

Disclaimer: Technical Operations Safety Action Program (T-SAP) Advisories contain important safety information. However, they are not directive in nature and do not supersede any directive or policy. For additional information on T-SAP, please visit our website at www.t-sap.org or call 877-360-6961.